Safe System of Work OPERATING AND SAFETY INSTRUCTIONS FOR LEISTER AIR GUN

1 Explain that safety equipment must be used at all times and why – safety boots must be used at all times when running machine. 2 Before operating Leister, inspect the electric cable for any damage, if cable is damaged report this to Manager or Setter and DO NOT USE. 3 Turn on Leister using isolator switch located above gun. 4 When operation of the Leister is required turn on using switch at the side of the green handle. Make sure electric cable is not close the nozzle gun. 5 When Leister has been running 20 seconds shrink wrapping may begin, Leister MUST be kept in holster provided whilst heating, only to be removed when shrink wrapping pipe fitting packs. 6 Only hold the Leister with the green handle. Do not touch the nozzle as this will be extremely hot and will burn. 7 Whilst shrink wrapping move the Leister around intended pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. 8 No heat shrinking to be done half an hour before the end of each shift. 9 Do not use any machine unless trained and authorised by Manager. ver received the above training and fully understand every point that was explained to firm that I will wear the required PPE equipment when using the above machinery are so to ensure my own safety. I will ask for further training if I need to and will immedia Supervisor or Manager if there are any issues with the machinery. me: Date: Date: nfirm that I have trained the aforementioned person and that they fully understand habove machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authorison to use the machinery detailed above.		Instruction	Understood ✓ or X
2 Before operating Leister, inspect the electric cable for any damage, if cable is damaged report this to Manager or Setter and DO NOT USE. 3 Turn on Leister using isolator switch located above gun. 4 When operation of the Leister is required turn on using switch at the side of the green handle. Make sure electric cable is not close the nozzle gun. 5 When Leister has been running 20 seconds shrink wrapping may begin, Leister MUST be kept in holster provided whilst heating, only to be removed when shrink wrapping pipe fitting packs. 6 Only hold the Leister with the green handle. Do not touch the nozzle as this will be extremely hot and will burn. 7 Whilst shrink wrapping move the Leister around intended pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. 8 No heat shrinking to be done half an hour before the end of each shift. 9 Do not use any machine unless trained and authorised by Manager. ver received the above training and fully understand every point that was explained to firm that I will wear the required PPE equipment when using the above machinery are so to ensure my own safety. I will ask for further training if I need to and will immedia Supervisor or Manager if there are any issues with the machinery. ne: Date: Infirm that I have trained the aforementioned person and that they fully understand habove machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authorison to use the machinery detailed above.	1	and why - safety boots must be used at all times when	
When operation of the Leister is required turn on using switch at the side of the green handle. Make sure electric cable is not close the nozzle gun. When Leister has been running 20 seconds shrink wrapping may begin, Leister MUST be kept in holster provided whilst heating, only to be removed when shrink wrapping pipe fitting packs. Only hold the Leister with the green handle. Do not touch the nozzle as this will be extremely hot and will burn. Whilst shrink wrapping move the Leister around intended pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. No heat shrinking to be done half an hour before the end of each shift. Do not use any machine unless trained and authorised by Manager. We received the above training and fully understand every point that was explained to the ex	2	Before operating Leister, inspect the electric cable for any damage, if cable is damaged report this to Manager	
When operation of the Leister is required turn on using switch at the side of the green handle. Make sure electric cable is not close the nozzle gun. When Leister has been running 20 seconds shrink wrapping may begin, Leister MUST be kept in holster provided whilst heating, only to be removed when shrink wrapping pipe fitting packs. Only hold the Leister with the green handle. Do not touch the nozzle as this will be extremely hot and will burn. Whilst shrink wrapping move the Leister around intended pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. No heat shrinking to be done half an hour before the end of each shift. Do not use any machine unless trained and authorised by Manager. Per received the above training and fully understand every point that was explained to the error that I will wear the required PPE equipment when using the above machinery are to ensure my own safety. I will ask for further training if I need to and will immediately error or Manager if there are any issues with the machinery. Date: Da	3	Turn on Leister using isolator switch located above gun.	
wrapping may begin, Leister MUST be kept in holster provided whilst heating, only to be removed when shrink wrapping pipe fitting packs. 6 Only hold the Leister with the green handle. Do not touch the nozzle as this will be extremely hot and will burn. 7 Whilst shrink wrapping move the Leister around intended pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. 8 No heat shrinking to be done half an hour before the end of each shift. 9 Do not use any machine unless trained and authorised by Manager. er received the above training and fully understand every point that was explained to the truth of the pack is to ensure my own safety. I will ask for further training if I need to and will immediate the pack is to ensure my own safety. I will ask for further training if I need to and will immediate the pack is to ensure my own safety. I will ask for further training if I need to and will immediate the pack is to ensure my own safety. I will ask for further training if I need to and will immediate the pack is the pack is the machinery. 9 Date: 10 Date: 11 Date: 12 Date: 13 Date: 13 Date: 14 Date: 15 Date: 16 Date: 17 Date: 18 Date: 18 Date: 19 Date: 10 Date: 10 Date: 10 Date: 11 Date: 12 Date: 13 Date: 14 Date: 15 Date: 16 Date: 17 Date: 18 Date: 18 Date: 18 Date: 19 Date: 10 Date: 10 Date: 10 Date: 10 Date: 11 Date: 12 Date: 13 Date: 14 Date: 15 Date: 16 Date: 17 Date: 18 Date: 18 Date: 19 Date: 10 Date: 10 Date: 10 Date: 10 Date: 11 Date: 12 Date: 13 Date: 14 Date: 15 Date: 16 Date: 17 Date: 18 Date: 18 Date: 18 Date: 19 Date: 10 Date: 10 Date: 10 Date: 10 Date: 11 Date: 12 Date: 13 Date: 14 Date: 15 Date: 16 Date: 17 Date: 18 Date		When operation of the Leister is required turn on using switch at the side of the green handle. Make sure electric	
the nozzle as this will be extremely hot and will burn. Whilst shrink wrapping move the Leister around intended pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. No heat shrinking to be done half an hour before the end of each shift. Do not use any machine unless trained and authorised by Manager. We received the above training and fully understand every point that was explained to firm that I will wear the required PPE equipment when using the above machinery are so to ensure my own safety. I will ask for further training if I need to and will immedia Supervisor or Manager if there are any issues with the machinery. Date: Date: Infirm that I have trained the aforementioned person and that they fully understand he above machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authorison to use the machinery detailed above.		When Leister has been running 20 seconds shrink wrapping may begin, Leister MUST be kept in holster provided whilst heating, only to be removed when shrink wrapping pipe fitting packs.	
pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When pack is cold a label may be attached. 8	6	· · · · · · · · · · · · · · · · · · ·	
of each shift. 9 Do not use any machine unless trained and authorised by Manager. e received the above training and fully understand every point that was explained to rm that I will wear the required PPE equipment when using the above machinery are to ensure my own safety. I will ask for further training if I need to and will immediately of any issues if there are any issues with the machinery. e: Date: firm that I have trained the aforementioned person and that they fully understand he bove machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authority to use the machinery detailed above.	7	pipe fitting pack, if you need to touch the pack use alley rod provided, do not touch pack for 20 seconds. When	
by Manager. e received the above training and fully understand every point that was explained to me that I will wear the required PPE equipment when using the above machinery are to ensure my own safety. I will ask for further training if I need to and will immediately approximately are any issues with the machinery. e: Date: firm that I have trained the aforementioned person and that they fully understand he bove machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authorism to use the machinery detailed above.	8		
firm that I will wear the required PPE equipment when using the above machinery are to ensure my own safety. I will ask for further training if I need to and will immedia Supervisor or Manager if there are any issues with the machinery. The control of the cont	9		
nfirm that I have trained the aforementioned person and that they fully understand he above machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authorison to use the machinery detailed above.	rm that s to ensi Supervis	I will wear the required PPE equipment when using the above ure my own safety. I will ask for further training if I need to an or or Manager if there are any issues with the machinery.	machinery and d will immediat
above machinery, have received the required PPE equipment and know to inform mediately of any issues with the machinery or if they require further training. I authorison to use the machinery detailed above.	ed:	Date:	
/ A the a wise	ifirm that above madiately	t I have trained the aforementioned person and that they fully achinery, have received the required PPE equipment and kno of any issues with the machinery or if they require further train	understand how w to inform me
ne:(Autnorise	e:		(Authorise