## **Plastica** Chelsea Premium Wooden Pool (Joined Wall) WPS110P

CODE	DESCRIPTION	QTY				
SPT018	837mm Treated Standard Plank	36				
SPT019	4628mm Treated Standard Plank	14				
SPT020	5650mm Treated Standard Plank R/H Drilled					
SPT021	5650mm Treated Standard Plank L/H Drilled	8				
SPT022	3978mm Treated Standard Plank R/H Drilled	8				
SPT023	3978mm Treated Standard Plank L/H Drilled	8				
SPT024	5750mm Treated Top Plank L/H Drilled	2				
SPT025	4078mm Treated Top Plank R/H Drilled	2				
SPT026	4828mm Treated Top Plank	1				
SPT027	1037mm Treated Top Half Plank	4				
SPT028	4628mm Treated Bottom Half Plank	2				
SPT029	3978mm Treated Bottom Half Plank L/H Drilled	2				
SPT030	5650mm Treated Bottom Half Plank R/H Drilled	2				
SPT147ENS	4828mm Treated Upper double Skimmer Plank to suit ENS110	1				
SPT137ENS	4628mm Treated Lower double Skimmer Plank to suit ENS110	1				
SPT174	4628mm Treated Inlet and Low Level Suction Plank	1				
HAU155NP	560mm Hardwood Ladder Tread New Pattern Sapele	4				
HIS5000NP	4383mm Hardwood Inside Top Shelf New Pattern Sapele	2				
HOS5000NP	4506mm Hardwood Outside Top Shelf New Pattern Sapele	2				
HIS1000NP	9383mm Hardwood Inside Top Shelf New Pattern Sapele	2				
HOS1000NP	9506mm Hardwood Outside Joined Top Shelf New Pattern Sapele	2				
HIS592NP	592mm Hardwood Inside Top Shelf New Pattern Sapele	4				
HOS715NP	716mm Hardwood Outside Top Shelf New Pattern Sapele	4				
SAT150	1390mm Treated Vertical Support Plank	24				
SAT701	250mm Treated Top Shelving Bracket (70mm)	32				
SAT700	1390mm Treated Vertical Support Plank (70mm)	10				
WPT600	1500mm treated wall end capping channel	16				
SAT070	1390mm Treated Metal Brace Cover	12				
SAT156R	1500mm Treated Wooden Step Side Right Hand	1				
SAT156L	1500mm Treated Wooden Step Side Left Hand	1				
LLO205	4600mm Sidemount Linerlock	6				
LLO204	3600mm Sidemount Linerlock	1				
KNO001	290mm Knocking Block	4				
STU1500	Studding M10 1.5M lengths	8				
WPK110P	Wooden Pools Fixing Kit for 5m x 10m Chelsea	1				

THIS PACK HAS BEEN PACKED AND CHECKED BY TWO PEOPLE THERE ARE NO PIECES DAMAGED OR MISSING.PLEASE RETAIN THIS SLIP INCASE OF REPLACEMENT PARTS NEEDED IN THE FUTURE

## W/O NUMBER

							-	D	R	Ρ
--	--	--	--	--	--	--	---	---	---	---

WPS110P WA2019